


+5V  
 -5V  
 TZ\_MOD  
 -8V  
 +12V  
 -12V  
 GND  
 Iabc



TRAP\_4  
 TRAP\_3  
 TRAP\_2  
 TRAP\_1  
 SQR\_4  
 SQR\_3  
 SQR\_2  
 SQR\_1

RUP\_4  
 RUP\_3  
 RUP\_2  
 RUP\_1  
 RDWN\_1  
 RDWN\_2  
 RDWN\_3  
 RDWN\_4

PWM\_4  
 PWM\_3  
 PWM\_2  
 PWM\_1  
 PWO\_1  
 PWO\_2  
 PWO\_3  
 PWO\_4

SIN\_1  
 SIN\_2  
 SIN\_3  
 SIN\_4  
 TRI\_1  
 TRI\_2  
 TRI\_3  
 TRI\_4

www.haraldswerk.de